JOHNSON ST.

DATE	PERMIT NUMBER	NUMBER OF STREET	OWNER	CONTRACTOR	COST	KIND OF BUILDING
4-19-72	6991A	923	Ronald King	Roary Corp	1,000.00	Aluminum Siding
4-28-72	7061-A	1006	Carl Meschner	O.B.	100.-	Remove frt porch add roof su, en. encl.
7/2/73	8810A	714	Robert Perry	OB	1440	rear addn to dwg.
9/9/76	2822B	1019	John Smith	R+H Remodeling	1000	Alum. Siding
8-15-77	4092B	924	J Dodson	Supreme Garage	3150	det gar.
11-14-77	4455B	924	Clara Dodson	Wickes Lumber	3,744	pri. det. garage
7-17-79	6761 B	836	Robert Spice	Scenic Enterprise	6,263	Front Porch & Alum. Siding
8-30-79	7031 B	1006	Carl Mescher	David L. Hugger	2,640	Move + Construct new basement for dwg.
9240B	9240B	916	R. Bill Shaw	OB	500	Rebuild exist open fr. porch
9348B	9348B	823	Eugene Rodriguez	OB	1,336.	Enclose Exist rear porch
9827B	9827B	719	Robert A. Reed	Roary Corp	3,075	Alum. Siding
7-30-82	1845C	728	Franklin C. Simmons, Jr.	OB	500.	Screen enclosure front porch
2-17-83	2451C	823	Aurora Rodriguez	K+E. Enterprises, Inc.	4,400.	C.O. Reroof fr. porch + new porch footings.
6-24-83	2959C	728	F. Simmons	Supreme Garage Co.	4,800.	Erect Pri-garage
10-7-83	3417C	728	F. Simmons	OB. Patio with Roof attached To garage.	924.	
3-20-84	3927C	915	Fransico Cortez	Friar Bldrs.	10,300.	C.O. repairs.
~~7-17-84~~	~~4590C~~	~~1007 N.~~	~~Darryl J. Brown~~	~~OB~~ CANCELLED 3/13/85	400.	Remove front porch & erect rear Deck
4-16-86	7261C	816	Heather Homes Co.	Lynn Folkert Bldrs	7,000	Bedroom Closet, change rear door
7-29-86	7815C	818	William Goodrich	OB	500.	Rear deck + Sliding gl Door
7-14-87	9288C	838	Richard King	OB	1,920	erect rear open wood dec
10-20-87	9775C	836	Hazel Spice	Lilla Const.	2,500	repair rear porch, siding, win
7-28-89	2712D	1007	David Ma Kara	OB	1,000	Vinyl siding
8-11-89	2791D	706	Quaker MANAgement	OB	7,500	Porch, Siding, & interior repairs
8-11-89	2792D	722	"	OB	8,500	Porch, Siding, interior repairs
~~8-11-89~~	~~2793D~~	~~834~~	~~" 5-1-91~~	~~OB~~	~~9,500~~	"
8-18-89	2852D	1021	Walt Beckner	OB	145	Repair rear addition
10-12-89	3145D	822	DAVID Sherman	John Mc Allister	17,800	rear addition front porch & sidi
11-13-89	3279D	838	Betty King	OB	300	Repair front porch
4/4/90	3728D	710	William Conant	OB	500	Repair front [illegible]

JOHNSON ST.

DATE	PERMIT NUMBER	NUMBER OF STREET	OWNER	CONTRACTOR	COST	KIND OF BUILDING
5/9/90	3922D	1015	Walt Beckner	OB	2,000	Vinyl siding
6/18/90	4108A	806	Thelma Onyon	Professional Builders	2,500	Alter Kitchen & Bath
8/19/91	6153D	820	Joseph C. Sloane	OB	2,400	Repair det/garage
9/27/91	6376D	1022	Albert L. Weck	OB	10,000	detached garage
5-30-92	7311 D	910	Jim Vandership	R. Dale Kennedy	5,500	INT. + EXT. Repairs
6/10/97	14360	1003	Betty Burley	OB	500	Repair porch roof

JOLLY RD.

DATE	PERMIT NUMBER	NUMBER OF STREET	OWNER	CONTRACTOR	COST	KIND OF BUILDING
2-11-72	6745A	1805-07	Schroeder Bldrs, Inc.	O.B.	34,560	1sty, 2 fam. Dwg.
2-18-72	6769A	923	Anna & Oscar Steen	"	4,680	Enlg 1 fam. Dwg.
3-27-72	6864A	521 E.	Louis Legg Jr.	H. Chaffee	40,000	Retail Sales Bldg
4-17-72	6974A	3223 W.	Ray Malkey	O. B.	2,000	Alt & Repr 1 fam Dwelling
4-26-72	7033A	2301 E.	Timberline Const Co.	O. B.	319,032. -	24 unit Apart Bldg
4-26-72	7034A	2303 E	" " "	" "	319,032. -	24 " " "
4-26-72	7035A	2401 E.	" " "	" "	319,032. -	24 " " "
4-26-72	7036A	2317 E.	" " "	" "	260,188. -	16 unit Town houses
4-26-72	7037A	2307 E.	" " "	" "	260,188. -	16 " "
4-26-72	7038A	2309 E.	" " "	" "	266,000. -	16 " "
4-26-72	7039A	2315 E.	" " "	" "	260,188. -	16 " "
4-26-72	7040A	2313 E.	" " "	" "	195,141. -	12 " "
4-26-72	7041A	2311 E.	" " "	" "	195,141. -	12 " "
4-26-72	7042A	2319 E.	" " "	" "	325,235. -	20 " "
4-26-72	7043A	2417 E.	" " "	" "	260,188. -	16 " "
4-26-72	7044A	2415 E.	" " "	" "	195,141. -	12 " "
4-26-72	7045A	2413 E.	" " "	" "	325,235. -	20 " "
4-26-72	7046A	2411 E.	" " "	" "	260,188. -	16 " "
4-26-72	7047A	2403 E.	" " "	" "	260,188. -	16 " "
4-26-72	7048A	2409 E.	" " "	" "	325,235. -	20 " "
4-26-72	7049A	2407 E.	" " "	" "	260,188. -	16 " "
4-26-72	7050A	2405 E	" " "	" "	195,141. -	12 " "
4-26-72	7051A	2305 E.	" " "	" "	61,754. -	Community Bldg. & Pool
4-28-72	7065-A	721 W.	Marathon Oil Co.	Porcelain Bldg. Prod.	4,000. -	Alter Service Station
5-23-72	7195A	1020 E.	E.L. West Co.	Doyett Quality Insul	1600	alter comm. bldg w/front ad
~~6-30-72~~	~~7401A~~	~~3373~~ 3211-13	~~KASSUBA DEV~~	Canal OB 8/7/74.	~~119,029~~	~~16 Unit APT~~
~~"~~	~~7402~~	~~3311-19~~ 3301-03	~~"~~	Canal 8/7/74	~~128,905~~	~~24 " "~~
~~"~~	~~7403~~	~~3301-07~~	~~"~~	~~"~~	~~128,905~~	~~" " "~~
~~"~~	~~7405~~	~~3201-11~~	~~"~~	~~"~~	~~128,905~~	~~" " "~~
~~"~~	~~7408~~	~~3315-19~~ 3313-15	~~"~~	Canal 8/7/74	~~321,436~~	~~" " "~~
~~"~~	~~7409~~	~~3219~~	~~"~~	~~"~~	~~5,130~~	~~Pool Pavilion~~